


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

| Run Summary |                           |                |                  |             |                  |                    |                    |
|-------------|---------------------------|----------------|------------------|-------------|------------------|--------------------|--------------------|
| Test ID     | Test Type                 | Date Inspected | Company / Super. | Nearest MH  | Ground Condition | Notification Made? |                    |
| D1028-163   | Dye                       | 4/27/2009      | ADS/TM           | S15GG1032MH | Dry              | NA                 |                    |
| Address     | 2601 Park Heights Terrace |                | Location         | Curb        | Status           | Public             | Source Catch Basin |



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

| Test ID                                  | Test Type | Date Inspected | Company / Super.     | Nearest MH           | Ground Condition          | Notification Made? |
|--|-----------|----------------|----------------------|----------------------|---------------------------|--------------------|
| D1028-163                                | Dye       | 4/27/2009      | ADS/TM               | S15GG1032MH          | Dry                       | NA                 |
| <b>Address</b> 2601 Park Heights Terrace |           |                | <b>Location</b> Curb | <b>Status</b> Public | <b>Source</b> Catch Basin |                    |

### Observations & Photos

**Obs\_ID** D1028-163-OB01

**Nearest MH** S15GG1032MH

**Comments** Dye observed 20.0 ft. downstream of S15GG1032MH. Infiltration runner at joint at 10 oclock.




**Picture** \D1028-163-OB01-P01.jpg

**Comments** 20.0 ft. downstream of S15GG1032MH along S15GG1032G1.

**Obs\_ID** D1028-163-OB02

**Nearest MH** S15GG1032MH

**Comments** Dye observed 23.0 ft. downstream of S15GG1032MH. Infiltration runner at joint at 5 oclock.



**Picture** \D1028-163-OB02-P01.jpg

**Comments** 23.0 ft. downstream of S15GG1032MH along S15GG1032G1.

---


# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

| Run Summary |  |                |                  |             |  |                    |        |             |
|-------------|--|----------------|------------------|-------------|--|--------------------|--------|-------------|
| Test ID     | Test Type  | Date Inspected | Company / Super. | Nearest MH  | Ground Condition   | Notification Made? |        |             |
| D1028-163   | Dye  | 4/27/2009      | ADS/TM           | S15GG1032MH | Dry  | NA                 |        |             |
|             |  |                |                  |             |  |                    |        |             |
| Address     | 2601 Park Heights Terrace  |                | Location         | Curb        | Status   | Public             | Source | Catch Basin |
|             |  |                |                  |             |  |                    |        |             |
| Obs_ID      | D1028-163-OB03   |                |                  | Obs_ID      | D1028-163-OB04   |                    |        |             |
| Nearest MH  | S15GG1032MH  |                |                  | Nearest MH  | S15GG1032MH  |                    |        |             |
| Comments    | Dye observed 25.5 ft. downstream of S15GG1032MH. Infiltration gusher at joint at 1 oclock. |                |                  | Comments    | Dye observed 29.0 ft. downstream of S15GG1032MH. Infiltration runner at joint at 5 oclock. |                    |        |             |



**Picture** \D1028-163-OB03-P01.jpg

**Comments** 25.5 ft. downstream of S15GG1032MH along S15GG1032G1.

---



**Picture** \D1028-163-OB04-P01.jpg

**Comments** 29.0 ft. downstream of S15GG1032MH along S15GG1032G1.

---



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

| Test ID   | Test Type | Date Inspected | Company / Super. | Nearest MH  | Ground Condition | Notification Made? |
|-----------|-----------|----------------|------------------|-------------|------------------|--------------------|
| D1028-163 | Dye       | 4/27/2009      | ADS/TM           | S15GG1032MH | Dry              | NA                 |

| Address | 2601 Park Heights Terrace | Location | Curb | Status | Public | Source | Catch Basin |
|---------|---------------------------|----------|------|--------|--------|--------|-------------|
|---------|---------------------------|----------|------|--------|--------|--------|-------------|

**Obs\_ID** D1028-163-OB05

**Nearest MH** S15GG1032MH

**Comments** Dye observed 29.0 ft. downstream of S15GG1032MH. Infiltration runner at joint at 8 oclock.

**Obs\_ID** D1028-163-OB06


**Nearest MH** S15GG1032MH

**Comments** Dye observed 32.0 ft. downstream of S15GG1032MH. Infiltration gusher at joint at 10 oclock.



**Picture** \D1028-163-OB05-P01.jpg

**Comments** 29.0 ft. downstream of S15GG1032MH along S15GG1032G1.



**Picture** \D1028-163-OB06-P01.jpg

**Comments** 32.0 ft. downstream of S15GG1032MH along S15GG1032G1.

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

| Test ID  | Test Type | Date Inspected | Company / Super.     | Nearest MH           | Ground Condition          | Notification Made?   |
|--|-----------|----------------|----------------------|----------------------|---------------------------|--|
| D1028-163  | Dye       | 4/27/2009      | ADS/TM               | S15GG1032MH          | Dry                       | NA   |
| <b>Address</b> 2601 Park Heights Terrace   |           |                | <b>Location</b> Curb | <b>Status</b> Public | <b>Source</b> Catch Basin |  |
| <b>Obs_ID</b> D1028-163-OB07   |           |                |                      |                      |                           | <b>Obs_ID</b> D1028-163-OB08   |
| <b>Nearest MH</b> S15GG1032MH  |           |                |                      |                      |                           | <b>Nearest MH</b> S15GG1032MH  |
| <b>Comments</b> Dye observed 32.0 ft. downstream of S15GG1032MH. Infiltration runner at joint at 1 oclock. |           |                |                      |                      |                           | <b>Comments</b> Dye observed 35.3 ft. downstream of S15GG1032MH. Infiltration runner at joint at 4 oclock. |



**Picture** \D1028-163-OB07-P01.jpg

**Comments** 32.0 ft. downstream of S15GG1032MH along S15GG1032G1.

---



**Picture** \D1028-163-OB08-P01.jpg

**Comments** 35.3 ft. downstream of S15GG1032MH along S15GG1032G1.

---

# Smoke and Dye Testing Summary

## High Level Sewershed


### Run Summary

| Run Summary       |   |                |                  |                   |  |                    |                           |
|-------------------|---|----------------|------------------|-------------------|--|--------------------|---------------------------|
| Test ID           | Test Type   | Date Inspected | Company / Super. | Nearest MH        | Ground Condition   | Notification Made? |                           |
| D1028-163         | Dye   | 4/27/2009      | ADS/TM           | S15GG1032MH       | Dry  | NA                 |                           |
| <b>Address</b>    | 2601 Park Heights Terrace   |                | <b>Location</b>  | Curb              | <b>Status</b>  | Public             | <b>Source</b> Catch Basin |
| <b>Obs_ID</b>     | D1028-163-OB09  |                |                  | <b>Obs_ID</b>     | D1028-163-OB10   |                    |                           |
| <b>Nearest MH</b> | S15GG1032MH   |                |                  | <b>Nearest MH</b> | S15GG1032MH  |                    |                           |
| <b>Comments</b>   | Dye observed 41.3 ft. downstream of S15GG1032MH. Infiltration runner at joint at 5 o'clock. |                |                  | <b>Comments</b>   | Dye observed at 41.3 ft. downstream of S15GG1032MH. Infiltration runner at joint at 8 o'clock. |                    |                           |



**Picture** \D1028-163-OB09-P01.jpg

**Comments** 41.3 ft. downstream of S15GG1032MH along S15GG1032G1.



**Picture** \D1028-163-OB10-P01.jpg

**Comments** 41.3 ft. downstream of S15GG1032MH along S15GG1032G1.

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed


### Run Summary

| Run Summary |                           |                |                  |             |                  |                    |                    |
|-------------|---------------------------|----------------|------------------|-------------|------------------|--------------------|--------------------|
| Test ID     | Test Type                 | Date Inspected | Company / Super. | Nearest MH  | Ground Condition | Notification Made? |                    |
| D1028-163   | Dye                       | 4/27/2009      | ADS/TM           | S15GG1032MH | Dry              | NA                 |                    |
| Address     | 2601 Park Heights Terrace |                | Location         | Curb        | Status           | Public             | Source Catch Basin |

**Obs\_ID** D1028-163-OB11

**Nearest MH** S15GG1032MH

**Comments** Dye observed 44.5 ft. downstream of S15GG1032MH. Infiltration runner at joint at 5 o'clock.



**Picture** \D1028-163-OB11-P01.jpg

**Comments** 44.5 ft. downstream of S15GG1032MH along S15GG1032G1.

---